

MINI Damage List

Type	Car part	Puncture tyre	Vegetation scratch	Scratched -6 cm	Scratched +6 cm	Dented -6 cm	Dented +6 cm	Dented +20 cm	Chip	Cracked	Missing	Stain / Cut / Burn
External	Antenna	0	0	0	0	0	0	0	0	40	40	0
Internal	Arm rest	0	0	0	0	0	0	0	0	360	360	350
Other	Baby seat G0, G1, G2	0	0	0	0	0	0	0	0	120	120	120
Other	Back carpet	0	0	0	0	0	0	0	0	60	60	60
Other	Back seat cover	0	0	0	0	0	0	0	0	280	280	280
Other	Back seat padding	0	0	0	0	0	0	0	0	460	460	460
Other	Back seat structure	0	0	0	0	0	0	0	0	850	850	850
Other	Battery charge	0	0	0	0	0	0	0	0	60	60	0
External	Bonnet	0	220	260	360	280	650	1100	0	1100	1100	1100
Other	Booster seat G3	0	0	0	0	0	0	0	0	60	60	60
Other	Car documents	0	0	0	0	0	0	0	0	450	450	0
Internal	Car mat	0	0	0	0	0	0	0	0	60	60	60
External	Car plate	0	0	0	0	120	220	350	0	460	460	460
Other	Car stereo	0	0	0	0	0	0	0	0	650	650	650
Internal	Cigarette lighter	0	0	0	0	0	0	0	0	60	60	0
Other	Clutch broken	0	0	0	0	0	0	0	0	1200	0	0
Internal	Courtesy light car	0	0	0	0	0	0	0	0	60	60	0
Internal	Dashboard	0	0	0	0	0	0	0	0	800	800	800
Internal	Driver seat	0	0	0	0	0	0	0	0	600	600	600
Other	Driver seat cover	0	0	0	0	0	0	0	0	280	280	280
Other	Driver seat padding	0	0	0	0	0	0	0	0	460	460	460
Other	Driver seat structure	0	0	0	0	0	0	0	0	850	850	850
External	Emblem front	0	0	0	0	0	0	0	0	120	120	120
External	Emblem rear	0	0	0	0	0	0	0	0	120	120	120
Other	Engine broken	0	0	0	0	0	0	0	0	5000	5000	0
Other	Engine flooding	0	0	0	0	0	0	0	0	5000	5000	0
External	External left rear view complete electric	0	0	120	220	0	0	0	0	560	560	560
External	External left rear view complete manual	0	0	120	220	0	0	0	0	560	560	560
External	External right rear view complete electric	0	0	120	220	0	0	0	0	560	560	560
External	External right rear view complete manual	0	0	120	220	0	0	0	0	560	560	560
External	Front bumper	0	80	220	400	280	660	1000	0	1000	1000	1000
Other	Front carpet	0	0	0	0	0	0	0	0	60	60	60
External	Front grid bumper	0	0	0	0	0	0	0	0	320	320	0
External	Fuel cap	0	0	0	0	0	0	0	0	60	60	60
Other	Fuel contaminated	0	0	0	0	0	0	0	0	750	0	0
External	Fuel flap	0	80	120	160	0	0	0	0	260	260	260
Other	Glove box	0	0	0	0	0	0	0	0	380	380	0
Other	GPS Navigator portable	0	0	0	0	0	0	0	0	350	350	0
Other	GPS support	0	0	0	0	0	0	0	0	30	30	30
External	Hailstorm	0	0	0	0	2000	2000	2000	0	2000	0	0
Other	Hat rack hard	0	0	0	0	0	0	0	0	360	360	360
Other	Hat rack tarp	0	0	0	0	0	0	0	0	360	360	350
Other	Head rest	0	0	0	0	0	0	0	0	180	180	180
Other	Ignition switch	0	0	0	0	0	0	0	0	660	660	0
Other	Inside roof living	0	0	0	0	0	0	0	0	600	600	600
Internal	Interior rear view mirror	0	0	0	0	0	0	0	0	220	220	220
Other	Interior sanification	0	0	0	0	0	0	0	0	160	0	0
Other	Jack	0	0	0	0	0	0	0	0	60	60	0
Other	Jacket high visibility	0	0	0	0	0	0	0	0	40	40	0
Other	Key	0	0	0	0	0	0	0	0	450	450	0
Other	Key lost	0	0	0	0	0	0	0	0	450	450	0
External	Left cover external rear view	0	80	140	200	0	0	0	0	300	300	300
External	Left door handle front	0	0	80	180	0	0	0	0	300	300	300
External	Left door handle rear	0	0	80	180	0	0	0	0	300	300	300
External	Left front door	0	80	220	460	220	560	760	0	1200	1200	1200
External	Left front door lock	0	0	0	0	0	0	0	0	750	750	0
External	Left front door window	0	0	0	0	0	0	0	260	660	660	660
External	Left front fixed glass	0	0	0	0	0	0	0	260	520	520	520
External	Left front fog light	0	0	0	160	0	0	0	0	280	280	280
External	Left front hubcap	0	0	80	120	0	0	0	0	120	120	120
External	Left front mudguard	0	80	220	380	220	560	900	0	900	900	900
External	Left front tire	60	0	0	0	0	0	0	0	220	220	220
External	Left front wheel alloy	0	0	180	240	0	0	0	0	380	380	0
External	Left front wheel rim	0	0	0	0	0	0	0	0	260	260	0
External	Left headlight	0	320	0	0	0	0	0	0	0	0	0
External	Left hand	0	0	160	260	0	0	0	0	820	820	0
External	Left lateral indicator light	0	0	0	0	0	0	0	0	280	280	280
External	Left mirror external rear view	0	0	0	0	0	0	0	0	120	120	0
External	Left rear door	0	80	220	460	220	560	760	0	1200	1200	1200
External	Left rear door window	0	0	0	0	0	0	0	260	660	660	660
External	Left rear fixed glass	0	0	0	0	0	0	0	260	520	520	520
External	Left rear fog light	0	0	0	160	0	0	0	0	280	280	280

vettura-mini-damage-list-0426

External	Left rear hubcap	0	0	80	120	0	0	0	0	120	120	120
External	Left rear mudguard	0	80	220	380	220	560	900	0	900	900	900
External	Left rear tire	60	0	0	0	0	0	0	0	220	220	220
External	Left rear wheel alloy	0	0	180	240	0	0	0	0	380	380	0
External	Left rear wheel rim	0	0	0	0	0	0	0	0	260	260	0
External	Left sill car	0	80	260	320	320	660	960	0	960	960	960
External	Left tail headlight	0	0	0	180	0	0	0	0	450	450	450
External	Left Xenon headlight	0	0	220	320	0	0	0	0	860	860	0
Other	Multitasking display	0	0	0	0	0	0	0	0	1200	1200	1200
Other	Oil cup broken	0	0	0	0	0	0	0	0	750	750	0
Internal	Passenger seat	0	0	0	0	0	0	0	0	600	600	600
Other	Passenger seat cover	0	0	0	0	0	0	0	0	280	280	280
Other	Passenger seat padding	0	0	0	0	0	0	0	0	460	460	460
Other	Passenger seat structure	0	0	0	0	0	0	0	0	850	850	850
Other	Pneumatic puncture	60	0	0	0	0	0	0	0	60	0	0
External	Rear bumper	0	80	280	400	280	660	1000	0	1000	1000	1000
External	Rear windshield	0	0	0	0	0	0	0	260	900	900	900
External	Rear windshield wiper	0	0	0	0	0	0	0	0	240	240	240
External	Reflector	0	0	0	0	0	0	0	0	320	320	0
External	Right cover external rear view	0	80	140	200	0	0	0	0	300	300	300
External	Right door handle front	0	0	80	180	0	0	0	0	300	300	300
External	Right door handle rear	0	0	80	180	0	0	0	0	300	300	300
External	Right front door	0	80	220	460	220	560	760	0	1200	1200	1200
External	Right front door lock	0	0	0	0	0	0	0	0	750	750	0
External	Right front door window	0	0	0	0	0	0	0	260	660	660	660
External	Right front fixed glass	0	0	0	0	0	0	0	260	520	520	520
External	Right front fog light	0	0	0	160	0	0	0	0	280	280	280
External	Right front hubcap	0	0	80	120	0	0	0	0	120	120	120
External	Right front mudguard	0	80	220	380	220	560	900	0	900	900	900
External	Right front tire	60	0	0	0	0	0	0	0	220	220	220
External	Right front wheel alloy	0	0	180	240	0	0	0	0	380	380	0
External	Right front wheel rim	0	0	0	0	0	0	0	0	260	260	0
External	Right headlight	0	320	0	0	0	0	0	0	0	0	0
External	Right hand	0	0	160	260	0	0	0	0	820	820	0
External	Right lateral indicator light	0	0	0	0	0	0	0	0	280	280	280
External	Right mirror external rear view	0	0	0	0	0	0	0	0	120	120	0
External	Right rear door	0	80	220	460	220	560	760	0	1200	1200	1200
External	Right rear door window	0	0	0	0	0	0	0	260	660	660	660
External	Right rear fixed glass	0	0	0	0	0	0	0	260	520	520	520
External	Right rear fog light	0	0	0	160	0	0	0	0	280	280	280
External	Right rear hubcap	0	0	80	120	0	0	0	0	120	120	120
External	Right rear mudguard	0	80	220	380	220	560	900	0	900	900	900
External	Right rear tire	60	0	0	0	0	0	0	0	220	220	220
External	Right rear wheel alloy	0	0	180	240	0	0	0	0	380	380	0
External	Right rear wheel rim	0	0	0	0	0	0	0	0	260	260	0
External	Right sill car	0	80	260	320	320	660	960	0	960	960	960
External	Right tail headlight	0	0	0	180	0	0	0	0	450	450	450
External	Right Xenon headlight	0	0	220	320	0	0	0	0	860	860	0
External	Roof	0	400	400	600	320	1200	2000	0	2000	2000	2000
Internal	Roof lining	0	0	0	0	0	0	0	0	600	600	600
Other	Safety belt	0	0	0	0	0	0	0	0	550	550	0
Other	SD card Navigator	0	0	0	0	0	0	0	0	400	400	400
External	Sill	0	0	80	120	60	120	120	0	120	120	120
Other	Snow chains	0	0	0	0	0	0	0	0	80	80	0
Other	Spare wheel	0	0	0	0	0	0	0	0	250	250	0
External	Spoiler front bumper	0	0	120	180	120	260	260	0	260	260	0
External	Spoiler rear bumper	0	0	120	180	120	260	260	0	260	260	0
Other	Stain removal seats	0	0	0	0	0	0	0	0	0	0	150
External	Sticker removal	0	0	0	0	0	0	0	0	200	200	200
Internal	Sun visor	0	0	0	0	0	0	0	0	80	80	80
Other	Tire compressor kit	0	0	0	0	0	0	0	0	150	150	0
Other	Trunk carpet	0	0	0	0	0	0	0	0	260	260	260
External	Trunk door	0	220	180	280	320	660	1100	0	1100	1100	1100
External	Trunk door handle	0	0	80	180	0	0	0	0	360	360	360
External	Trunk door lock	0	0	0	0	0	0	0	0	750	750	0
External	Undercarriage	0	80	260	320	320	660	960	0	960	960	0
Other	Warning triangle	0	0	0	0	0	0	0	0	60	60	60
External	Windshield	0	0	0	0	180	0	0	260	900	900	900
External	Windshield wiper	0	0	0	0	0	0	0	0	240	240	240
External	Wreck	0	0	0	0	0	0	0	0	2000	2000	0
Other	Wrong refuelling	0	0	0	0	0	0	0	0	750	0	0

Criteria for Damage Assessment

The amounts shown in this table are expressed in euro and are not subject to VAT, as they relate to charges of a compensatory nature pursuant to Article 15(1) of Presidential Decree No. 633/1972. Damage is assessed on the basis of the part concerned, the type of damage and, where applicable, its extent measured in centimetres. A **scratch** is a superficial or linear mark affecting the paintwork or material; a **vegetation scratch** is a mark caused by contact with branches, brambles or other vegetation; a **dent** is a deformation of the part, with categories for damage up to 6 cm, over 6 cm and over 20 cm; a **chip** is localised damage involving loss of material; a **crack or breakage** is damage affecting the integrity of the part; a **missing part** is the total or partial absence of a component or one of its elements; a **stain, cut or burn** is damage affecting a surface or trim; a **tyre puncture** is damage that compromises the integrity or usability of the tyre. Scratches are classified as up to 6 cm or over 6 cm. Where the damage results in impairment of the part, the loss of part of it, or the need for repair or replacement, the corresponding item set out in the table shall apply.